



IN-TANK TECHNOLOGY



(Prices Effective January 2009)

FLO KING BXL2500 FACTORY REPAIR SERVICE & PARTS

DESCRIPTION	ORDER NO.	PRICE IN USA
1. Motor replacement (includes motor pulley)	2500 MOTOR	325.00
2. Reconditioned motor (available only with exchange of reconditionable motor)	2500 MRC	225.00
3. Motor bearing replacement	2500 MB	85.00
4. Fan cover	2500 FCOV	20.00
5. Fan blade replacement (includes hardware)	2500 FBR	12.00
6. Fan blade hardware	2500 FBHW	2.00
7. Capacitor cover	2500 CAPCOV	15.00
8. Capacitor replacement	2500 CAPR	20.00
9. Line cord installation (includes line cord restraint)	2500 LC	20.00
10. Line cord restraint	2500 LCR	9.50
11. Switch replacement	2500 SWITCH	16.00
12. Switch boot cover	2500 SBC	3.50
13. Switch guard	2500 SGR	7.00
14. Switch box	2500 SB	28.50
15. Switch box cover	2500 SBXC	10.00
16. Switch box hardware	2500 SBHW	2.25
17. Adjustable standoff	2500 ASO	17.00
18. Strip and clean pump	2500 STRIP	20.00
19. Boot seal	2500 VBS	10.00
20. Shaft balance and alignment	2500 BAL	20.00
21. Teflon tubing (shaft coating)	2500 TEF	1.00/inch
22. Spacer replacement for pump base (each)	2500 SPC	3.00
23. Teflon-coated shaft with shaft pulley & bearings (old style)†	2500 SHPB ___ (length)*	200.00
23a. Teflon-coated shaft with SS shaft pulley & bearings (new style)†	2500 NSHPB ___ (length)*	200.00
24. Motor pulley replacement (old style)†	2500 PR	35.00
24a. Motor pulley replacement (SS, new style)†	2500 NPR	42.00
25. Body replacement**	2500 BR ___ (length)*	80.00
26. Pump base**	2500 PB	60.00
27. Pump base hardware	2500 PBHW	5.00
27a. Pump base & body replacement **	2500 BBR ___ (length)*	135.00
28. Impeller replacement (includes shaft balance/alignment)	2500 IMPB	55.00
29. Impeller washer	2500 TIW	3.00
30. Super slinger	2500 TSS	6.00
31. Swiveling impeller housing replacement	2500 SHR	125.00
32. Lock screw for swiveling impeller housing	2500 SHLS	2.25
33. Teflon strap for swiveling impeller housing	2500 STRAP	7.00
34. Upper stage plate	2500 USP	14.00
35. Flow plate replacement (old style)	2500 FLP	12.00
36. Filter screw replacement (each)	2500 FS	2.25
37. Plug and retap filter screw holes (each)	2500 TAP	5.00
38. Motor base assembly with heel, 12" (includes belt)†	2500 MB12	250.00
39. Motor base assembly with heel, 15" (includes belt)†	2500 MB15	275.00
40. Motor base hardware	2500 MBHW	5.00
41. Belt for 12"-long motor base (old style)†	2500 B12	12.00
41a. Belt for 12"-long motor base (new style)†	2500 NB12	27.50
42. Belt for 15"-long motor base (old style)†	2500 B15	17.50
42a. Belt for 15"-long motor base (new style)†	2500 NB15	30.00
43. Belt replacement, 12" (new style, includes belt & factory installation) †	2500 NBR12	34.00
44. Belt replacement, 15" (new style, includes belt & factory installation)†	2500 NBR15	36.00
45. Belt drive cover for 12"-long motor base	2500 BDC12	40.00
46. Belt drive cover hardware for 12"-long motor base	2500 BDCHW12	5.00
47. Belt drive cover for 15"-long motor base	2500 BDC15	55.00
48. Belt drive cover hardware for 15"-long motor base	2500 BDCHW15	3.00
49. Belt drive cover reinforcement strip	2500 BDCRS	4.00
50. Pump shaft bearing replacement	2500 PSBR	80.00
51. Rework motor base	2500 MBR	26.00
52. Heel	2500 MBH	80.00

* Pump body length and material of construction must be specified when ordering these parts. To determine pump body length, measure "A" dimension as shown on Bulletin 14.5 illustration.

** For repairs in the field, order Item 27a (pump base and body replacement) to avoid machining operations associated with separate purchase of either pump body (Item 25) or pump base (Item 26).

† BXL2500 units purchased prior to Dec. 2002 use aluminum pulleys with "old style" belts. Units manufactured as of Dec. 2002 use stainless-steel pulleys and "new style" belts. BXL2500 units sent to factory for repair will be upgraded to SS pulleys and new-style belt.

Material of Construction: Specify pump material of construction when ordering parts. Most units are made of CPVC (gray in color) or polypropylene (white). Kynar (PVDF) and stainless steel are also used.

Special Shaft Material: Add \$10 for titanium-tip shaft. Add \$25 for Hastelloy C-tip shaft. Tip is 2" (5-cm) long, threads onto impeller, and can be installed on BXL2500-10, 12 and 14" pump-body lengths.