



(Prices Effective January 2011)

FLO KING BXL5000 FACTORY REPAIR SERVICE & PARTS

DESCRIPTION	ORDER NO.	PRICE
1. Motor replacement (includes motor pulley)	50XL MOTOR	350.00
2. Reconditioned motor (available only with exchange of reconditionable motor)	50XL MRC	250.00
3. Motor bearing replacement	50XL MB	85.00
4. Fan cover	50XL FCOV	24.00
5. Fan blade replacement (includes hardware)	50XL FBR	13.00
6. Fan blade hardware	50XL FBHW	2.00
7. Capacitor cover	50XL CAPCOV	15.00
8. Capacitor replacement	50XL CAPR	20.00
9. Line cord installation (includes line cord restraint)	50XL LC	20.00
10. Line cord restraint	50XL LCR	9.50
11. Switch replacement	50XL SWITCH	16.00
12. Switch boot cover	50XL SBC	3.50
13. Switch guard	50XL SGR	7.00
14. Switch box	50XL SB	30.00
15. Switch box cover	50XL SBXC	12.00
16. Switch box hardware	50XL SBHW	2.25
17. Adjustable standoff	50XL ASO	17.00
18. Strip and clean pump	50XL STRIP	20.00
19. Boot seal	50XL VBS	10.00
20. Shaft balance and alignment	50XL BAL	20.00
21. Teflon tubing (shaft coating)	50XL TEF	1.00/inch
22. Spacer replacement for pump base (each)	50XL SPC	3.00
23. Teflon-coated shaft with shaft pulley & bearings (old style)†	50XL SHPB ___ (length)*	210.00
23a. Teflon-coated shaft with SS shaft pulley & bearings (new style)†	50XL NSHPB ___ (length)*	200.00
24. Motor pulley replacement (old style)†	50XL PR	30.00
24a. Motor pulley replacement (SS, new style)†	50XL NPR	42.00
25. Body replacement**	50XL BR ___ (length)*	80.00
26. Pump base**	50XL PB	60.00
27. Pump base hardware	50XL PBHW	5.00
27a. Pump base & body replacement **	50XL BBR ___ (length)*	135.00
28. Impeller replacement (includes shaft balance/alignment)	50XL IMPB	65.00
29. Impeller washer	50XL TIW	3.00
30. Super slinger	50XL TSS	6.00
31. Swiveling impeller housing replacement	50XL SHR	125.00
32. Lock screw for swiveling impeller housing	50XL SHLS	2.25
33. Teflon strap for swiveling impeller housing	50XL STRAP	7.00
34. Upper stage plate	50XL USP	14.00
35. Flow plate replacement (old style)	50XL FLP	12.50
36. Filter screw replacement (each)	50XL FS	2.25
37. Plug and retap filter screw holes (each)	50XL TAP	5.00
38. Motor base assembly with heel (includes belt)†	50XL MB15	275.00
39. Motor base hardware	50XL MBHW	5.00
40. Belt (old style)†	50XL B15	17.50
40a. Belt (new style)†	50XL NB15	30.00
41. Belt replacement (new style, includes belt and factory installation)	50XL NBR15	35.00
42. Belt drive cover	50XL BDC15	55.00
43. Belt drive cover hardware	50XL BDCHW15	3.00
44. Pump shaft bearing replacement	50XL PSBR	80.00
45. Rework motor base	50XL MBR	25.00
46. Heel	50XL MBH	80.00

* Pump body length and material of construction must be specified when ordering these parts. To determine pump body length, measure "A" dimension as shown on Bulletin 14.2 illustration.

** For repairs in the field, order Item 27a (pump base and body replacement) to avoid machining operations associated with separate purchase of either pump body (Item 25) or pump base (Item 26).

† BXL5000 units purchased prior to Dec. 2002 use aluminum pulleys with "old style" belts. Units manufactured as of Dec. 2002 use stainless-steel pulleys and "new style" belts. BXL5000 units sent to factory for repair will be upgraded to SS pulleys and new-style belt.

Material of Construction: Specify pump material of construction when ordering parts. Most units are made of CPVC (gray in color) or polypropylene (white). Kynar (PVDF) and stainless steel are also used.