



IN-TANK TECHNOLOGY



ABOUT OUR FACTORY REPAIR SERVICE AND PARTS

WE STRONGLY RECOMMEND THAT YOU TAKE ADVANTAGE OF OUR FACTORY REPAIR SERVICE.

- **PRICES:** THE PRICES SHOWN BELOW INCLUDE BOTH PARTS AND INSTALLATION BY OUR FACTORY. IN MOST CASES, PRICES ARE THE SAME FOR PARTS ALONE.
- **SERVICE:** OUR REPAIR DEPARTMENT IS STAFFED BY TRAINED TECHNICIANS AND PROVIDED STRICTLY AS A SERVICE TO **FLO KING** USERS.
- **RETURN PROCEDURE:** **IMPORTANT! CLEAN EQUIPMENT IN ACCORDANCE WITH SHIPPING REGULATIONS. SEND TO: REPAIR DEPT., CUSTOM MASTERS INC., 401 LAKE BENNETT CT., LONGWOOD, FL 32750-6341 USA.** MAKE SURE TO INCLUDE YOUR NAME, ADDRESS, AND PHONE NUMBER SO THAT THE REPAIR TECHNICIAN CAN CONTACT YOU WITH AN EVALUATION AND ESTIMATE. A RETURN AUTHORIZATION NUMBER IS NOT REQUIRED. USE OF THE ORIGINAL **FLO KING** BOX AND PACKING WILL RESULT IN SECURE TRANSPORT OF YOUR EQUIPMENT.

(Prices Effective January 2011)

FLO KING LAB SERIES FACTORY REPAIR SERVICE & PARTS

DESCRIPTION	ORDER NO.	PRICE
1. Motor replacement (includes shaft alignment), 110 volt	LAB MOTOR	\$75.00
220 volt		85.00
2. Motor with balanced Teflon-coated shaft attached (includes motor plate), 110 volt	LAB MOTSHF ___ (length)* . .	140.00
220 volt		145.00
3. Motor cover	LAB MCOV	35.00
4. Motor cover repair	LAB MCR	18.00
5. Motor cover screen	LAB MCS	18.00
6. Fan blade replacement	LAB FBR	6.00
7. Line cord installation (includes line cord restraint)	LAB LC	12.00
8. Line cord with switch (includes installation and restraint)	LAB LCS	20.00
9. Motor plate	LAB MP	20.00
10. Spacer replacement for pump/motor base (each)	LAB SPC	2.50
11. Shaft with Teflon coating (includes balance/alignment)	LAB SHAFT ___ (length)*	45.00
12. Shaft balance and alignment (factory repair only)	LAB BAL	15.00
13. Body and housing replacement (factory repair only)	LAB BHR**	77.00
14. Pump/motor base replacement	LAB PBR	35.00
14a. Pump/motor base, body & impeller housing	LAB PBBH ___ (length)**	112.00
15. Housing outlet replacement (discharge port)	LAB HO	18.00
16. Flow plate replacement	LAB FLP	6.00
17. Impeller replacement (includes shaft balance/alignment)	LAB IMP	28.00
18. Upper stage plate	LAB USP	8.00
19. Plug and retap filter screw holes	LAB TAP	5.00
20. Filter screw replacement	LAB FS	3.00
21. Strip and clean pump	LAB STRIP	15.00
22. Washer seal for motor plate	LAB RWS	4.00

* Pump body length must be specified when ordering these parts. Measure "A" dimension as shown on Bulletin 16 illustration.
 ** For repairs in the field, order Item 14a (combination Pump/Motor Base, Body & Impeller Housing to avoid machining operations associated with separate purchase of Pump/Motor base (Item 13), Body (Item 14), and/or Impeller Housing (Item 16). Specify pump body length when ordering.

Pioneers of In-Tank Filtration ★ www.floking.com

CUSTOM MASTERS, INC. • 401 LAKE BENNETT CT., LONGWOOD, FL 32750-6341 USA • 407-331-4634 FAX 407-331-0575

Prices are subject to change without notice. Prices are F.O.B. Longwood, Florida, and do not include local, state or federal taxes.